



Department of Transport

# Repair Design Certificate

**This approval is issued to:**

AvWIND INTERNATIONAL  
6415 Northwest Drive  
Mississauga, ONTARIO  
L4V 1X1 CANADA

**Number:** O-RA02-034

**Issue No.:** 2

**Approval Date:** May 15, 2002

**Issue Date:** July 25, 2002

**Responsible Office:**

Ontario

**Aircraft/Engine Type or Model:**

Per Eligibility List No. AV-100

**Registration/Serial No.:**

N/A

**Canadian Type Certificate or Equivalent:**

AvWind International Quality Control Directive No: QCP-011,  
[Engineering Function] revision 0, and report No. R02052,  
Revision 1, Paragraphs 2.0 and 3.0.

**Description of Repair Design Change:**

Component Rewind Repairs


**Installation/Operating Data,  
Required Equipment and Limitations:**

Repair / Refurbishment of AC Exciter Rotors (AWX) in accordance with AvWind International Eligibility List: AV-100, dated 05/04/02, or later Transport Canada Approved revision.

-- END --

**Conditions:** This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair and any other modification(s) incorporated **will not** adversely affect the airworthiness of the modified product.



  
Alex Pompei  
For Minister of Transport