

Department of Transport Repair Design Certificate

This approval is issued to:	Number: O-RA02-035
AvWIND INTERNATIONAL	Issue No.: 2
6415 Northwest Drive	Approval Date: May 16, 2002
Mississauga, ONTARIO	Issue Date: July 25, 2002
L4V 1X1 CANADA	
Responsible Office:	Ontario
Aircraft/Engine Type or Model:	Per Eligibility List No. AV-100
Registration/Serial No.:	N/A
Canadian Type Certificate or Equivalent:	AvWind International Quality Control Directive No: QCP-011,
	[Engineering Function] revision 0, and report No. R02052,
	Revision 1, Paragraphs 2.0 and 3.0.
Description of Repair Design Change:	Component Powind Panaira
Description of Repair Design Change:	Component Rewind Repairs

Installation/Operating Data, Required Equipment and Limitations:

Repair/Refurbishment of AC stators (AWG/AWP) in accordance with AvWind International Eligibility List: AV-100, dated 05/04/02, or later Transport Canada Approved revision.

-- END --

Conditions: This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair and any other modification(s) incorporated **will not** adversely affect the airworthiness of the modified product.



Alex Pompei For Minister of Transport

a forger

