Department of Transport

Repair Design Certificate

This approval is issued to:

Number: O-RA02-036

AvWIND INTERNATIONAL

Issue No.: 2

6415 Northwest Drive Mississauga, ONTARIO

Approval Date: May 16, 2002

L4V 1X1 CANADA

Issue Date: July 25, 2002

Responsible Office:

Ontario

Aircraft/Engine Type or Model:

Per Eligibility List No. AV-100

Registration/Serial No.:

N/A

Canadian Type Certificate or Equivalent:

AvWind International Quality Control Directive No: QCP-011,

[Engineering Function], revision 0, and report No. R02052,

Revision 1, Paragraphs 2.0 and 3.0.

Description of Repair Design Change:

Component Rewind Repairs

Installation/Operating Data,
Required Equipment and Limitations:

Repair/Refurbishment of Exciter Stators (AWM / AWY) in accordance with AvWind International Eligibility List: AV-100, dated 05/04/02, or later Transport Canada Approved revision.

Conditions: This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair and any other modification(s) incorporated **will not** adversely affect the airworthiness of the modified product.

Alex Pompei For Minister of Transport

