



# Repair Design Certificate

**This approval is issued to:**

AvWind International  
6611 Edwards Blvd.  
Mississauga, Ontario  
Canada L5T 2H8

**Number:** O-RA02-034

**Issue No.:** 4

**Approval Date:** May 15, 2002

**Issue Date:** September 15, 2021

**Responsible Office:**

Ontario

**Aircraft/Engine Type or Model:**

Per Eligibility List No: AV-100

**Serial No.:**

Process RDA

**Canadian Type Certificate or Equivalent:**

AvWind International Quality Control Directive No. QCP-011,  
[Engineering Function] Revision 3.0 and Report No: R02052,  
Revision 3.0, Paragraphs 2.0 and 3.0.

**Description of Type Design Change:**

Component Rewind Repairs

**Installation/Operating Data,  
Required Equipment and Limitations:**

Repair / refurbishment of AC Exciter Rotors (AWX) in accordance with AvWind International Eligibility List No: AV-100, dated 05/04/02, or later Transport Canada approved revisions.

- END -

**Conditions:** This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this modification, the installer shall establish that the interrelationship between this change and any other modification(s) incorporated **will not** adversely affect the airworthiness of the modified product.

DocuSigned by:

C8F2E41099B341A...

Albert Leung  
For Minister of Transport