

## **Department of Transport**

## Repair Design Certificate

This approval is issued to:

Number: O-RA02-030

**AvWIND INTERNATIONAL** 

Issue No.: 2

6415 Northwest Drive

Approval Date: May 07, 2002

Mississauga, ONTARIO L4V 1X1 CANADA Issue Date: July 16, 2002

Responsible Office:

Ontario

Aircraft/Engine Type or Model:

Per Eligibility List No. AV-100

Registration/Serial No.:

N/A

**Canadian Type Certificate or Equivalent:** 

AvWind International Quality Control Directive No: QCP-011,

[Engineering Function] revision 0, and report No. R02052,

Revision 1, Paragraphs 2.0 and 3.0.

**Description of Repair Design Change:** 

**Component Rewind Repairs** 

Installation/Operating Data,
Required Equipment and Limitations:

Repair / Refurbishment of DC Stators (AWS/AWF) in accordance with AvWind International Eligibility List: AV-100, dated 05/04/02, or later Transport Canada Approved revision.

-- END --



**Conditions:** This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair and any other modification(s) incorporated **will not** adversely affect the airworthiness of the modified product.

Alex Pompei For Minister of Transport

Alex Penger

