

Department of Transport Repair Design Certificate

This approval is issued to:	Number: O-RA02-033	
AvWIND INTERNATIONAL	Issue No.: 2	
6415 Northwest Drive	Approval Date: May 15, 2002	
Mississauga, ONTARIO	Issue Date: July 16, 2002	
L4V 1X1 CANADA		
Responsible Office:	Ontario	
Aircraft/Engine Type or Model:	Per Eligibility List No. AV-100	
Registration/Serial No.:	N/A	
Canadian Type Certificate or Equivalent:	AvWind International Quality Control Directive No: QCF [Engineering Function] revision 0, and report No. R02052 Revision 1, Paragraphs 2.0 and 3.0.	
Description of Repair Design Change:	Component Rewind Repairs	

Installation/Operating Data, Required Equipment and Limitations:

Repair / Refurbishment of AC Rotors (AWR) in accordance with AvWind International Eligibility List No: AV-100, dated 05/04/02, or later Transport Canada Approved revision.

-- END --

Conditions: This approval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair and any other modification(s) incorporated **will not** adversely affect the airworthiness of the modified product.



Alex Pongu Alex Pompei For Minister of Transport

